

**COMMONWEALTH GARAGE REPAIRS 2007 - 2010**

Project Contact – Pat Perry; Spencer Sullivan

Since 2007, Structural Services, Inc. has prepared construction documents for 4 separate repair projects totaling approximately \$800,000. Repairs included slab reinforcement due to broken post tension cables and column and beam repairs due to embedded steel and reinforcement corrosion. Additionally, slab reinforcement was added at the columns adjacent to the Hyatt Regency Hotel due to concrete deterioration that had reduced the shear capacity of the slab to unsafe levels.



Beam Repair in progress at Commonwealth Garage

Temporary shoring and new shear head reinforcement at Commonwealth Garage

